FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 - 1970)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)		
Name of the School : ST. PAUL'S ENGLISH MEDIUM SCHOOL		
1.	Name of the Officer	: Vimalkumar V Assi Engineer
2.	Location	: Taliparamba
3.	Period for which the certificate is issued	2025-26
4.	Types of building	: Permanent RCC Building.
5.	Nature of defect if any	
	a) Foundation and basement	1. 35.40 x 8.60 x 3.70 GF, FF,
	b) Superstructure	: 2. 6 40 x 5. 50 x 3. 70 (GF, FF, S
	c) Doors and windows	3. 57.20 X8.80X3.70 (G+)
	d) Wood work wrought and put up	4. 15.30×6.60 × 2.40 (allar floor
	e) Roof	5 35 30 x 8 -708 x 3 -70 (OF)
	f) Flooring	6. 42.70 x 8.70 x 2.70 x 48.84 40.4
	g) Miscellaneous (Cracks if any)	:7. 44.40×8-70, ×3.70 & 4.84×8.40×
6.	Any Major defects notices which will render the building unsafe in any manner	: 7. 44.40×8-70, ×3.70 (FF-Lsh.) 10×84×8.40×
7.	Whether maintenance works have been done properly	: YES
8.	Whether the structure is sound or not for conducting classes	: YES under normal wealher Condition.
Note:- 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc. 2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.		
CERTIFICATE		
Certified that the School was inspected by me on 27 95 2025		
and found to be fit / unfit to conduct classes for the perioduptaMarch 2026		
for the reason stated above.		
Plac	ce: Toliparamba (Sea	Municipal Engineer
Date:27 05 2025 Talipa mamba Municipality		
		Assistant Engineer
തളിപ്പാന് പു ത്യിക്കാര്യാ		
		്ള് . തളിപ്പറമ്പ് പി. ഒ.

തളിഷന്ത നഗരസഭ